

Rights of Way Unresolved Issues Report : Bicester & Kidlington

Please help Oxfordshire County Council manage its backlog of network issues more effectively by reporting your information in the table below. Please include whether you consider that the issue is resolved or not, inspection dates and references to any photos. In particular, please tell us about those issues which have not been reported within the last 3 years - highlighted in yellow.

Please add any new issues you find by using our interactive website reporting system at <https://camsv.oxfordshire.gov.uk/>

Launton

Path & Issue Code	OCC Issue Database Record 23 October 2018	PPW Report: Resolved or unresolved and comments
Footpath 1 SP6147,2276	Crossing/Bridge or Culvert Repair: Bridge in fair condition but inspect in 24 months Priority: 4a CAMs Ref: 24076	1 plank and 1 step show signs of rot. East end support falling into stream needs new support beams.
Footpath 1 SP6221,2277	Last actioned/Last reported: Crossing/Bridge or Culvert Repair: Bridge ok but should be inspected in 2 years Priority: 4a CAMs Ref: 24075	OK for now.
Footpath 1 SP6298,2291	Last actioned/Last reported: Crossing/Bridge or Culvert Repair: Some signs of rot, inspect in 24 months Priority: 4a CAMs Ref: 24074	On county boundary Some signs of rot.
Footpath 1 SP6294,2290	Last actioned/Last reported: Crossing/Boardwalk Repair or Replace: Tree down across the bridge Priority: 4a CAMs Ref: 24072	Boardwalk sits below winter water level and shows signs of rot. Fallen tree threatens to fall further and block path - chain saw required
Footpath 1 SP6202,2277	Last actioned/Last reported: Apr 17 Surface/Drainage Required: Whole route liable to flooding. Ditches need clearing out Priority: 3 CAMs Ref: 22650	Over this winter but no ditching has been done.
Bridleway 2 SP6251,2217	Last actioned/Last reported: Jul 16 Crossing/Bridge or Culvert Required: Bridge Survey. Sat under trees, decks showing very early signs of wear. Inspect again 24-36 months. Bridlegate on each end Priority: 4a CAMs Ref: 20317	2 Planks have been replaced but a further 2 showing signs of rot.
Last actioned/Last reported: Apr 16		



OXFORDSHIRE COUNTY COUNCIL

Rights of Way Unresolved Issues Report : Bicester & Kidlington

Please help Oxfordshire County Council manage its backlog of network issues more effectively by reporting your information in the table below. Please include whether you consider that the issue is resolved or not, inspection dates and references to any photos. In particular, please tell us about those issues which have not been reported within the last 3 years - highlighted in yellow.

Please add any new issues you find by using our interactive website reporting system at <https://camsv.oxfordshire.gov.uk/>

Launton

Path & Issue Code	OCC Issue Database Record 23 October 2018	PPW Report: Resolved or unresolved and comments
Bridleway 2 Start: SP6119,2271 End: SP6123,2267 Length(m): 63	Obstacles/Building on Path: Definitive route blocked by sheds and vehicles. Bridleway used on alternative alignment Priority: 2c CAMs Ref: 22652	Definitive map route has been blocked for over 40 years. I am contacting 'Blitz and Klean'
Bridleway 2 SP6206,2224	Last actioned/Last reported: Jul 16 Surface/Drainage Required: Various flooding along bridleway, ditches need clearing out Priority: 3 CAMs Ref: 22653	I would describe gateway as a muddy FOD ok for riders or animals but not walkers so could a gate or stile be provided.
Footpath 5 SP6043,2234	Last actioned/Last reported: Jul 16 Crossing/Bridge or Culvert Repair: Bridge beams rotten Priority: 2a CAMs Ref: 25970	Resolved
Footpath 5 SP6045,2238	Last actioned/Last reported: Crossing/Bridge or Culvert Repair: Some rot in sleepers Priority: 3 CAMs Ref: 26072	Resolved
Footpath 5 SP6041,2230	Last actioned/Last reported: Surface/Drainage Required: Water on path crating very wet and muddy area Priority: 2c CAMs Ref: 26071	Resolved (Partly) but hardcore or old paving slabs would improve much used path.
Footpath 7 SP6013,2272	Last actioned/Last reported: Stile/Repair or Replace: Rickety stile - New one needed Priority: 4a CAMs Ref: 22655	likely to be replaced by E.W. Rail in connection with new road bridge nearby.
Last actioned/Last reported: Jul 16		



OXFORDSHIRE COUNTY COUNCIL

Rights of Way Unresolved Issues Report : Bicester & Kidlington

Please help Oxfordshire County Council manage its backlog of network issues more effectively by reporting your information in the table below. Please include whether you consider that the issue is resolved or not, inspection dates and references to any photos. In particular, please tell us about those issues which have not been reported within the last 3 years - highlighted in yellow.

Please add any new issues you find by using our interactive website reporting system at <https://camsv.oxfordshire.gov.uk/Launton>

Launton

Path & Issue Code	OCC Issue Database Record 23 October 2018	PPW Report: Resolved or unresolved and comments
Footpath 9 SP6057,2298	Obstacles/Building on Path: Path obstructed by sports hall, however can be easily be walked around Priority: 4a CAMs Ref: 04879	<i>DMs Needed.</i> <i>Who is responsible for this?</i>
Footpath 10 SP6087,2284	Last actioned/Last reported: May 07 Jul 16 Surface/Drainage Repair: Reported that building work adjacent to the footpath has caused flooding on the RoW. Priority: 4a CAMs Ref: 19855	<i>Parish Clerk is chasing builders to deal with drainage problems</i>
Footpath 10 SP6089,2290	Last actioned/Last reported: Jan 15 Jan 15 Jan 15 Surface/Drainage Required: surface around stile is flooded and impassable Priority: 2c CAMs Ref: 25793	<i>before it will accept this play area.</i>
Footpath 15 SP6013,2324	Last actioned/Last reported: Crossing/Bridge or Culvert Repair: PPW advises bridge needs handrail Priority: 4a CAMs Ref: 22657	<i>Safety Concerns.</i>
Footpath 20 SP6208,2481	Last actioned/Last reported: Jul 16 Gate/Request: Gate Required Priority: 4c CAMs Ref: 04249	<i>Stile lacks step.</i>
Footpath 20 SP6159,2398	Last actioned/Last reported: Feb 07 Crossing/Bridge or Culvert Repair: Bridge will need to be replaced in due course. LO will be doing ditching work so we will need to undertake work once this is done Priority: 4a CAMs Ref: 22674	<i>Ditching work in progress.</i> <i>Stile at this location uprights rotten.</i> <i>Debris from hedge cutting obstructing path.</i>



OXFORDSHIRE COUNTY COUNCIL

Rights of Way Unresolved Issues Report : Bicester & Kidlington

Please help Oxfordshire County Council manage its backlog of network issues more effectively by reporting your information in the table below. Please include whether you consider that the issue is resolved or not, inspection dates and references to any photos. In particular, please tell us about those issues which have not been reported within the last 3 years - highlighted in yellow.

Please add any new issues you find by using our interactive website reporting system at <https://camsv.oxfordshire.gov.uk/>

Launton

Path & Issue Code	OCC Issue Database Record 23 October 2018	PPW Report: Resolved or unresolved and comments
Footpath 20 SP6218,2505	Crossing/Bridge or Culvert Repair: AFO Inspected - Bridge showing signs of rot and will need replacing soon. Priority: 2a CAMs Ref: 23749	Bridge very rotten needs replacing urgent. Handrail adrift + unsafe.
Footpath 20 SP6175,2409	Last actioned/Last reported: Feb 17 Crossing/Bridge or Culvert Repair: Landowner is going to install a culvert where the old bridge has been removed. Shallow ditch so not a hazard in the meantime Priority: 4a CAMs Ref: 22673	Ditch has now been dug out so Culvert or bridge required urgently. debris from Hedge cutting left on path.
Footpath 20 SP6207,2480	Last actioned/Last reported: Aug 16 Finger Post/Repair or Replace: Missing Priority: 4a CAMs Ref: 23907	Replaced last year.
Footpath 22 Start: SP6176,2453 End: SP6193,2451 Length(m): 172	Last actioned/Last reported: Ploughing Cropping/Cropping Cross Field Path: Footpath not reinstated Priority: 3 CAMs Ref: 22659	Field now grass and path well marked.

Foot path 17
6022364 to 60342380
Diversed Path does not extend to meet old path but ends in a 10ft high earth bank planted with trees. It only joins a permissive path which could be closed. Good Path but no waymarks.

Foot path 19
60302360 to 60082390
This path has been obliterated by developers. There is no path or even a single way mark to indicate its route

NEW PROBLEMS.

Oxfordshire Ramblers PPW Report Form

Name and Number of Parish LANTON 272 Name of PPW JOHN BOYSEN.

This Form is to be used to report NEW problems and any problems previously reported that have worsened significantly

Path No.	Dates Inspected	Grid ref. Position	Nature of Problem	Work needed or done	Landowner or manager details if known	OCC issue reference
1	Feb 2019	6260 2080	F.B. Missing. Remains lie in muddy ditch.	Bridge required as alternative gateway is under water	v/k.	
BW2	Feb 2019	6237 2217	FB 3 Planks Rotten	Please repair as horse could easily break planks	v/k.	
BW2	2019	6251 2217	FB 2 Planks Rotten	Repair / Replace URGENT. Well used path.	Hawes Family +	
11	Feb 2019	6096 2323	Stile uprights rotten + broken only secured by wire Remains rock alarmingly. UNSAFE	Only one stile is required. This is an obstruction to deer walkers	Sycamore Horse Lounton	
12	Jan 2019	6121 2323	THREE stiles in two yards. southern stile is much too high and impossible to average walker.		DEELEY FAMILY MANOR FARM	
13	Jan 2019	6126 2363	Stile uprights rotten + broken Signs of rot to bridge.		DEELEY FAMILY.	

11/13/14/20

VAPLOUS. CROSS FIELD PATHS NOT MARKED OR REINSTATED. CROP NOW 14" high

Mark route with weedkiller

Many locals tell me this are deterred from walking as they do not know route at these paths.